

FOR ALUMINUM LOUVERS

CAUTION

FOLLOWING PART INSTALLATION, PLEASE CAREFULLY LIFT REAR HATCH OR TRUNK LID TO ENSURE PROPER ALIGNMENT AND FIT. IN SOME CASES, HINGES SAG OR PREVIOUS VEHICLE DAMAGE REPAIRS MAY CAUSE IMPROPER GAP DIMENSIONS TO THE HATCH OR TRUNK. IT IS ALSO NOT UNCOMMON FOR REPAINTED VEHICLES TO HAVE A “MATERIAL” BUILD UP, CHANGING THE PANELS’ FACTORY GAP DIMENSIONS. THIS COULD LEAD TO PAINT OR PART DAMAGE TO THE ROOF PANEL OR THE TOP EDGE OF THE TRUNK PANEL.

WILLPAK INDUSTRIES INC. WILL NOT BE HELD RESPONSIBLE FOR ANY VEHICLE DAMAGE CAUSED IN THIS REGARD.